

115

TECHNICAL REPORT

Warning during assembly
process of rocker cover
gasket 11023900



PURPOSE

To report to the customer about the importance of making a **correct tightening** process during the assembly process of rocker cover gasket **11023900**.



DESCRIPTION

Throughout history, from Technical Support Department of AJUSA, we have detected a **common mistake** which is made during the assembly process of the rocker cover gasket 11023900.

This gasket is made of rubber and has a slot around all its perimeter which must be **introduced by the cover edge**. Afterwards, the cover will be screwed to the head by two bolts. An **excessive torque** or higher than recommended by the manual in each application **might damage or cut the gasket**.

Next, we are going to show you some examples where we have been able to see **how gasket has been damaged** and cut after receiving an excessive torque.





An **excessive torque** or higher than recommended by the manual in each application might **damage or cut the rocker cover gasket** 11023900.

ASSEMBLY VIDEOS

Through next videos you can follow the **completely assembly process** of the rocker cover gasket 11023900.

