

# SKF Technik Bulletin

## VKBA 6543 – Erforderlicher Austausch der Staubschutzringe



VOLVO C30, C70 II, S40 II, V50



**Erforderlicher Austausch der Staubschutzringe beim Radlagerwechsel**



OE Nr: 31340604

Nach OE-Vorgaben soll der Staubschutzring bei jedem Radlagerwechsel mit gewechselt werden. Deshalb hat SKF den Kit-Inhalt bei dem Radlagerkit VKBA 6543 ab Produktionscode 24 O geändert und die Staubschutzringe im Kit beigefügt. Die alten Ringe müssen immer ersetzt werden, da diese bei den Ausbaurbeiten beschädigt werden können.

**Achtung!** Welcher mitgelieferte Staubschutzring verwendet werden muss ist abhängig von der Antriebswellenlänge! Überprüfen Sie vor dem Einbau des Radlagers die Länge der Antriebswelle.



7 mm

Für lange Antriebswellen

9,5 mm

Für kurze Antriebswellen

VKBA 6543



**YouTube** [Click here to watch SKF technical videos on Youtube!](#)

© SKF Group 2017

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use

